[Designation of Document] Abstract
[Abstract]

10

15

[Problems to be solved] It is to provide a method for forming a rubber strip which enables a wider rubber of small thickness without lowering an extruding speed and enables to reduce a building cycle time, thereby increasing the efficiency of tire manufacturing.

[Means for Solving the Problems] Temperatures at a main-part casing 11, a screw shaft 12 and a head region included with the die 13 are controlled to be different from each other in a manner that: the temperature as controlled in the main-part casing 11 is higher than that in the screw shaft 12; and the temperature as controlled in the head region is higher than that in the main-part casing 11, when continuously extruding a rubber material in a form of a ribbon in forming a rubber strip 1.